

»» | ALEOS 4.11.1 Release Notes

ALEOS 4.11.1 is for AirLink® LX40 and LX60 Series routers. The AirLink LX40 is a compact LTE and LTE-M / NB-IoT router for IoT/M2M applications.

New Features

Radio Modules

With release 4.11.1, both the LX60 and LX40 support the following radio modules:

WP7601

- Verizon: SWI9X07Y_02.10.00.00

WP7603

- Generic: SWI9X07Y_02.10.01.00
- AT&T: SWI9X07Y_02.10.01.00

WP7607

- Generic: SWI9X07Y_02.16.02.00

WP7609

- Generic: SWI9X07Y_02.18.05.00

WP7702

- AT&T: SWI9X06Y_02.16.06.00
- Generic: SWI9X06Y_02.16.06.00

Note: For LTE-M/NB-IoT (WP7702) AirLink routers: Due to the lower data rates supported by LTE-M/NB-IoT networks, over-the-air software updates can take an extended period of time. When using a Windows PC and ACEmanager to update ALEOS software over-the-air, please ensure that sleep and low power states are disabled on the PC so that the file transfer is not disrupted. Under these conditions, the ALEOS upgrade may take between 3 to 5 hours.

Sierra Wireless recommends using ALMS or AMM for remote software upgrades.

ALEOS AT Commands

The LX40 USB port is used for AT commands.

Cellular

Added LTE IoT Operating Mode (displayed in Status > Cellular > Advanced).

Wi-Fi

LX40 Wi-Fi model indicates Wi-Fi status on the Network LED. See “LED Behavior” in the AirLink LX40 Hardware User Guide for more information.

Location

LX60: The Location Status in ACEmanager now also shows the GPS antenna status:

- Connected
- Open
- Shorted

Logging

Added the ability to download logs in a compressed format to optimize data usage.

POE

LX40 supports Power over Ethernet (PoE). When both V_{in} and PoE are available, the device uses PoE. When using PoE, the device can never enter standby mode via the On/Off control line.

Security Enhancements

Security and CVE Vulnerabilities

Addressed potential vulnerabilities related to CVE-2018-1000122 (see <https://nvd.nist.gov/vuln/detail/CVE-2018-1000122>)

General

Enhanced security of remote access operations.

An option to set the minimum TLS version is now available under Admin > Advanced.

Bug Fixes

ACEmanager

Resolved an issue where the top row of command buttons were appearing inconsistently when switching between tabs.

- The Defaults button no longer appears in the Status, Wi-Fi, or Events Reporting tab when switching from the Log submenu.
- The Delete button no longer appears in the Status tab when switching from the Events Reporting tab.

Wi-Fi

LX60: Resolved an issue where more than one Access Point was shown on the Status > Wi-Fi page.

Resolved an issue where an invalid (fewer than 7 characters) Client Password for WPA/WPA2 Personal would disappear after clicking Apply. A notification that the password must be between 8 and 125 characters will now appear after an invalid password is entered.

The default setting for “Allow Clients to See One Another” is now Enable.

Note: Resetting the device to factory default will enable this feature.

VLAN

Resolved an issue where the VLAN bridge MAC address did not match the AirLink MAC address.

Events Reporting

LX60: Binary, XML and CVS are now available in the Actions Type list for Events Reporting.

Logging

Resolved an issue where a log message incorrectly reported the radio module temperature level.

To reduce flash usage, certain statistics for VPN tunnel are no longer available in the logs.

Services

Fixed a race condition issue with SSH key generation.

Ethernet

MAC address is now displayed correctly in the Status > Ethernet field.