

iSMA-B-LP

Room Panel with LCD

iSMA-B-LP Software Bundle 2.3.1

23 Apr 2020

The list below contains modifications and new features since the release of software bundle version 2.1.1.

NAME	DESCRIPTION
iSMA-B-LP Ver. 2.3.1 Release date 23 Apr 2020	Improvements: <ul style="list-style-type: none">• added Watchdog;• improved CO2 sensor filter. Fixed Bugs: <ul style="list-style-type: none">• fixed bug with CO2 sensor malfunction.

iSMA-B-LP Software Bundle 2.1.1

26 Jun 2018

The list below contains modifications and new features since the release of software bundle version 2.1.0.

NAME	DESCRIPTION
iSMA-B-LP Ver. 2.1.1 Release date 26 Jun 2018	Fixed Bugs: <ul style="list-style-type: none">• fixed bug with main menu blocking error when the lowest priority was given to the variable with numeric type.

iSMA-B-LP Software Bundle 2.1.0

14 Jun 2018

The list below contains modifications and new features since the release of software bundle version 2.0.18.

NAME	DESCRIPTION
iSMA-B-LP Ver. 2.1.0 Release date 14 Jun 2018	Fixed Bugs: <ul style="list-style-type: none">• fixed bug with temperature measurement error.

iSMA-B-LP Software Bundle 2.1.0

14 Jun 2018

The list below contains modifications and new features since the release of software bundle version 2.0.18.

NAME	DESCRIPTION
iSMA-B-LP Ver. 2.1.0 Release date 14 Jun 2018	Fixed Bugs: <ul style="list-style-type: none">• fixed bug with temperature measurement error.

The list below contains modifications and new features since the release of software bundle version 2.0.17.

NAME	DESCRIPTION
iSMA-B-LP Ver. 2.0.18 Release date 31 Jan 2018	Improvements: <ul style="list-style-type: none">improved firmware to increased range of LCD test for pin 4. Fixed Bugs: <ul style="list-style-type: none">fixed bug with LCD test error;fixed bug with component BV11.

The list below contains modifications and new features since the release of software bundle version 1.0.18.

NAME	DESCRIPTION
iSMA-B-LP Ver. 2.0.17 Release date 31 Aug 2017	New Functionalities: <ul style="list-style-type: none">BACnet protocol support;added information about Hardware Version HW_VERSION (Modbus register 3031, BACnet Device object, property 3020);added information about CO2 Alarm Status CO2_ALARM_STATUS (Modbus register 30230, BACnet Binary Input objects no. 0 and 1) Improvements: <ul style="list-style-type: none">improved CO2 alarm functionality – possibility of confirmation the alarm and activation alarm indications (Flashing LCD, Buzzer, Show HIGH) locally from the panel;improved flashing of the 'Occupied' icon with a synchronization to flashing of the Fan Icons group;improved CO2_SENSOR_OFFSET values, now without decimal place, the default value is 10;improved TEMPERATURE_SENSOR_OFFSET values, now negative values are possible;improved parameters are written down to the EEPROM every 2 seconds (240 seconds before); Fixed Bugs: <ul style="list-style-type: none">fixed parameters displaying order after re-entering the submenu;fixed displaying AM and PM icons in 12h time display mode;fixed conversion between temperature units – °C and °F;fixed reading of Modbus register values after startup or restart.

The list below contains modifications and new features since the release of software bundle version 1.0.17.

NAME	DESCRIPTION
iSMA-B-LP Ver. 1.0.18 Release date 21 Feb 2017	<p>New Functionalities:</p> <ul style="list-style-type: none"> added SubmenuIconDisplayOFF bit in DeviceConfiguration register to disable Submenu Icons displaying. <p>Improvements:</p> <ul style="list-style-type: none"> improved displaying numbers – added digit „0” before the first dot. <p>Fixed Bugs:</p> <ul style="list-style-type: none"> fixed bug with displaying negative values in submenus and Main menu; fixed bug with displaying boolean values in submenus and Main menu; fixed bug with displaying units and dots in submenus in the case when numeric and Boolean type values were together inside the same submenu; fixed bug with displaying default password when the new password was entered; fixed bug with displaying occupancy icon when the register OccupancyCurrentStatus value equals 3; fixed bug with transition between submenus when one of them was protected by password; fixed bug with SubmenuIconFlashing register.

NAME	DESCRIPTION
iSMA-B-LP Ver. 1.0.17 Release date 29 Nov 2016	First release.